

# Interim Reclamation and Stormwater Inspection

January 11, 2021

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 441811

Inspection Document #: 697502419

Weld County, CO

NWSW Section 5 T2N R68W


Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** The above imagery illustrates the approved Fairview/5-I Pad access route.



**Photo 2.** The above imagery illustrates an unapproved access route that is being utilized (red dashed line). Refer to Photos 3- regarding the unapproved access route.



**Photo 3.** Photo taken from the approved oil and gas access road, facing Southwest. Photo illustrates a portion of an unapprove access route that has been utilized. Vehicle traffic is departing the access road traveling southwest to access Fairview St. On January 7, 2021, Extraction put up temporary barriers to prohibit further use.



Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 4.** Photo taken from Fairview St, facing South. Photo illustrates no evidence of vehicle track out at the time of this inspection. City of Longmont stated there was some damage to Smuckers vegetation due to this vehicle traffic. Snow cover prevented further investigation of that matter.



**Photo 5.** Photo taken from Fairview St, facing North. See comments under Photo 4.



Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 6.** Photo taken from the entrance of the access road off Hwy 119, facing Northwest. Photo illustrates the entrance/exit portion of access road- from the cattle guard (red circle) to Hwy 119- has been sufficiently stabilized with recycled asphalt. There was no evidence of vehicle rutting or vehicle track out, which further indicates the access road has been sufficiently stabilized.





Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 7.** Photo taken from the entrance of the access road off Hwy 119, facing West. Photo illustrates no evidence of vehicle track out at the time of this inspection.





Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 8.** Photo taken from a portion of the northern access road, facing South. Photo illustrates the access road has been sufficiently stabilized and there was no evidence of vehicle rutting.



Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 9.** Photo taken from the southeastern location, facing West. Photo illustrates Extraction has performed interim reclamation to reduce all disturbance area only needed for production operations.



**Photo 10.** Photo taken from the southeastern location, facing Northwest. See comments under Photo 9.





Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 11.** Photo taken from the southeastern location, facing West. Photo illustrates a ditch and berm BMP, which is directed to a stabilized outlet along the southeastern location.



**Photo 12.** Photo taken from the southeastern location, facing North. See comments under Photo 11.

Inspection Photos  
Location Name: Fairview /5-I Pad  
Location ID: 441811



**Photo 13.** Photo taken from the southeastern location, facing Southeast. Photo illustrates the stabilized outlet BMP. At the time of this inspection, all BMPs are in proper functioning condition.

