



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type LOCATION

Comment: 6" chain link with brown slats

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bird Protectors # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 1

Comment: automation

Corrective Action:

Date: \_\_\_\_\_

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Bradenhead # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: <span style="color:blue;">shares contianment with oil tank</span>	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 278796 Type: WELL API Number: 001-09542 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection location of gas meter run was unknown. At time of inspection weather conditions were cold, cloudy, recent snow.	medinaj	01/12/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502132	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328478">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328478</a>