

Inspection Photos
Operator: Simcoe
API: 067-06295
Date: 1/11/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner. Revegetation is progressing in portions of the project area with western wheatgrass and Indian ricegrass. Portions of the interim area remain weedy and need to be monitored.



Photo 3. View of the eastern project area facing northward.



Photo 4. View of reference area comprised of sagebrush shrubland with a mix of grasses and forbs such as buckwheat, blue grama, and western wheatgrass.