

Inspection Photos
Operator: High River Resources
API: 067-07306
Date: 1/11/2021



Photo 1. View of the project area from the northeastern corner facing center. Location is shared with two Red Willow wells.



Photo 2. View of the northern project area from the northeastern corner facing westward. Vegetation is in a grazed and dormant vegetative condition and needs to be monitored during the active growing season.



Photo 3. View of the eastern project area facing southward.



Photo 4. View of reference area comprised of open grass field in a grazed/dormant vegetative condition.