

Inspection Photos
Operator: Simcoe
API: 067-05157
Date: 1/11/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Stormwater controls such as berm and cobble lined diversion, are installed and need to be monitored and maintained for function.



Photo 3. View of the eastern project area facing northward.



Photo 4. View of reference area comprised of a crop field in a non-vegetative condition at this time.