

Inspection Photos

Operator: High River Resources
API: 067-07316
Date: 1/11/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of erosional channel, approx. 2-3 ft wide and deep, in the southern project area.



Photo 3. View of the southern project area facing eastward. Multiple erosional channels are present.



Photo 4. View of another erosional channel in the southern project area, approx. 4-5 feet wide and 2-3 feet deep.



Photo 5. View of well area, no evidence of well sign observed.



Photo 6. View of reference area comprised of sagebrush shrubland with western wheatgrass, sand dropseed, and buckwheat. Project area is above irrigation alignment.