

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/05/2021

Submitted Date:

01/14/2021

Document Number:

688800847

**FIELD INSPECTION FORM**
 Loc ID 325536 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Heil, John		john.heil@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214965	WELL	PR	12/03/2012	GW	067-06570	GOSNEY 1	EI
463850	Domestic Tap	AC	04/10/2019		-	Domestic Tap 14NWNW	EI

**General Comment:**

On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1. For the most recent field inspection report of this facility, please refer to document #687904955.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign mounted to separator shack.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Tank battery signs have previous operator and emergency contact information listed.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 02/15/2021
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Cables near well head.		
Corrective Action:	Comply with Rule 603.f.		Date: 01/29/2021
Type	STORAGE OF SUPL		
Comment:	Two track hoes and a loader stored on site.		
Corrective Action:	Comply with Rule 603.f.		Date: 01/29/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Jersey barriers protecting well head and separator.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Other	# 1		
Comment:	Domestic tap.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	NE marker is down.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		37.193111,-107.582173
Comment:	Tank battery on #1A location.				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

**Wells Served By Facilities Above**

API Number
067-09255
067-06729
067-09798
067-09507
067-06570

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	214965	Type:	WELL	API Number:	067-06570	Status:	PR	Insp. Status:	EI
Facility ID:	463850	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on south load out line.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1. For the most recent field inspection report of this facility, please refer to document #687904955.</p> <p>Heavy equipment is being stored on location. Unused cables are being stored near the well head. A section of abandoned flow line, noted in previous inspections, was observed off of the eastern edge of the location. Comply with Rule 603.f. Corrective action dates are listed within this document.</p> <p>The remote tank battery signs have the previous operator and emergency contact information listed.</p>	hughesjo	01/14/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800848	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329824">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329824</a>