

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2021

Submitted Date:

01/13/2021

Document Number:

699802409

FIELD INSPECTION FORM

Loc ID 334103 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273408	WELL	PR	09/01/2017	GW	045-10246	HYRUP 2-68	PR
290196	WELL	PR	06/01/2014	GW	045-14035	HYRUP 2-34C (2O)	PR
290245	WELL	SI	01/01/2020	GW	045-14056	HYRUP 2-44B	SI
290246	WELL	PR	01/01/2011	GW	045-14067	HYRUP 2-34B (2O)	PR
290247	WELL	PR	09/01/2017	GW	045-14066	HYRUP 2-34A	PR
290252	WELL	SI	01/01/2020	GW	045-14061	HYRUP 11-41B (2O)	SI
290253	WELL	SI	10/01/2020	GW	045-14060	HYRUP 11-41A	SI
290254	WELL	PR	09/01/2017	GW	045-14059	HYRUP 11-31A (2O)	PR
290255	WELL	SI	02/01/2020	GW	045-14058	HYRUP 2-44D	SI
290256	WELL	PR	04/30/2010	GW	045-14057	HYRUP 2-44C	PR
290258	WELL	PR	06/29/2010	GW	045-14055	HYRUP 2-44A	PR

General Comment:

[COGCC Inspection Report Summary](#)
 On Wednesday 1/13/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at CAERUS PICEANCE LLC HYRUP /2-34B, Location #334103 in Garfield County Colorado.
 While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed: Multiple holes in tank containment liner. See photo #2623 and #2624 with a corrective action date of 2/23/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:	No form of pressure monitoring located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Multiple holes in tank containment liner. See photo #2623 and #2624				
Corrective Action:	Secondary containment structures shall be sufficiently impervious to contain discharged material. Repair all holes in tank containment liner.			Date:	02/23/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities										
Facility ID:	273408	Type:	WELL	API Number:	045-10246	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:							Date:			
Facility ID:	290196	Type:	WELL	API Number:	045-14035	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:							Date:			
Facility ID:	290245	Type:	WELL	API Number:	045-14056	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder:							
Comment:	Last produced December 2019									
Corrective Action:							Date:			
Facility ID:	290246	Type:	WELL	API Number:	045-14067	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:							Date:			
Facility ID:	290247	Type:	WELL	API Number:	045-14066	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:							Date:			
Facility ID:	290252	Type:	WELL	API Number:	045-14061	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder:							
Comment:	Last produced December 2019									
Corrective Action:							Date:			
Facility ID:	290253	Type:	WELL	API Number:	045-14060	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder:							
Comment:	Last produced September 2020									
Corrective Action:							Date:			
Facility ID:	290254	Type:	WELL	API Number:	045-14059	Status:	PR	Insp. Status:	PR	

Producing Well	
Comment: Producing	
Corrective Action:	Date:

Facility ID: 290255 Type: WELL API Number: 045-14058 Status: SI Insp. Status: SI

Idle Well	
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____	
Comment: Last produced January 2020	
Corrective Action:	Date: _____

Facility ID: 290256 Type: WELL API Number: 045-14057 Status: PR Insp. Status: PR

Producing Well	
Comment: Producing	
Corrective Action:	Date:

Facility ID: 290258 Type: WELL API Number: 045-14055 Status: PR Insp. Status: PR

Producing Well	
Comment: Producing	
Corrective Action:	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Sediment Traps				
Gravel						
		Culverts				
Sediment Traps						
Berms						
		Gravel				
		Berms				
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802410	Photos for Insp. #699802409	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329825