

Inspection Photos

API: 099-06328

Operator: BERRY ENERGY INC

Inspection Date: 1/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06328 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing east along the former access road toward the location. Vegetation has not adequately re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06328 | Date: 1/12/2021

Inspection Photos



Photo 2. Pipe riser remains at the center of the location. Lat/Long:37.95992,-102.50066



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06328 | Date: 1/12/2021

Inspection Photos



Photo 3. Facing west toward the location. Vegetation has not adequately re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06328 | Date: 1/12/2021

Inspection Photos



Photo 4. Facing east toward the location. Vegetation has not adequately re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06328 | Date: 1/12/2021

Inspection Photos



Photo 5. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06328 | Date: 1/12/2021