

Inspection Photos

API: 099-06139

Operator: BERRY ENERGY INC

Inspection Date: 1/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing south toward the location. The location is bare of vegetation and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos



Photo 2. West side of the location. Pipe riser has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos




Photo 3. An additional pipe riser has not been removed at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos



Photo 4. Facing north toward the location. The location is bare of vegetation and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos




Photo 5. Facing east at the northeast side of the location. This erosion gully extends out into the pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021