

Inspection Photos

ID: 431431

Operator: STRACHAN EXPLORATION INC

Inspection Date: 1/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 431431 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing south toward the Prowers Gas Gathering Co Fluid tank. There is no location sign posted per Rule 210.b.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 431431 | Date: 1/12/2021

Inspection Photos



Photo 2. The labeling of the tank is missing information per Rule 210.d.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 431431 | Date: 1/12/2021

Inspection Photos



Photo 3. Facing north toward the compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 431431 | Date: 1/12/2021

Inspection Photos



Photo 4. There is oil stained soil around the compressor and on the compressor skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 431431 | Date: 1/12/2021

Inspection Photos



Photo 5. Facing toward meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 431431 | Date: 1/12/2021