

Inspection Photos

API: 099-06215

Operator: BERRY ENERGY INC

Inspection Date: 1/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing west toward the location. The location has not been recontoured. The cut slope is shown in this photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021

Inspection Photos



Photo 2. Facing southeast toward the access road. There is erosion gully along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021

Inspection Photos



Photo 3. Facing north at the location. This area has no vegetation growth. Soils seem to be compacted in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021

Inspection Photos



Photo 4. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021

Inspection Photos



Photo 5. There are pipe risers that remain at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021

Inspection Photos



Photo 6. This pipe riser remains at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 1/12/2021