

Inspection Photos
Operator: Simcoe
API: 067-05226
Date: 1/11/2021



Photo 1. View of the plugged well and reclaimed project area facing northward. Plugged well marker is yellow.



Photo 2. View of seeding along the access road facing southward. Drill rows are visible.



Photo 3. View of the southern project area facing eastward. Vegetation is well established. Partial snow covering present.



Photo 4. View of reference area comprised of irrigated grass field with Baltic rush, Timothy, and other irrigated grasses.