

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2021

Submitted Date:

01/15/2021

Document Number:

700405012

FIELD INSPECTION FORM

 Loc ID 335946 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 OGCC Operator Number: 100264
 Name of Operator: XTO ENERGY INC
 Address: 110 W 7TH STREET
 City: FORT WORTH State: TX Zip: 76102
Contact Information:

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-675-4122	jessica_dooling@xtoenergy.com	
West, Jerry		jerry_west@xtoenergy.com	
Clark, Erin	405-319-3250	erin_clark@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286172	WELL	PR	10/01/2012	GW	103-10867	PICEANCE CREEK UNIT 297-11A5	PR
286173	WELL	PR	11/06/2009	GW	103-10866	PICEANCE CREEK UNIT 297-11A4	PR
286174	WELL	PR	03/15/2011	GW	103-10865	PICEANCE CREEK UNIT 297-11A3	PR
286175	WELL	PR	05/29/2009	GW	103-10864	PICEANCE CREEK UNIT 297-11A2	PR
286176	WELL	PR	06/10/2009	GW	103-10863	PICEANCE CREEK UNIT 297-11A1	PR
286177	WELL	PR	07/17/2009	GW	103-10862	PICEANCE CREEK UNIT 297-11A6	PR
286178	WELL	PR	05/27/2009	GW	103-10861	PICEANCE CREEK UNIT 297-11A9	PR
286179	WELL	PR	01/01/2019	GW	103-10860	PICEANCE CREEK UNIT 297-11A8	PR
286180	WELL	PR	03/15/2011	GW	103-10859	PICEANCE CREEK UNIT 297-11A7	PR

General Comment:

Routine well inspection.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Telemetry.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: Chemical containers.			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	RTU building & well manifold.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 11		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	286172	Type:	WELL	API Number:	103-10867	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286173	Type:	WELL	API Number:	103-10866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286174	Type:	WELL	API Number:	103-10865	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286175	Type:	WELL	API Number:	103-10864	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286176	Type:	WELL	API Number:	103-10863	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286177	Type:	WELL	API Number:	103-10862	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286178	Type:	WELL	API Number:	103-10861	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	286179	Type:	WELL	API Number:	103-10860	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Facility ID: 286180 Type: WELL API Number: 103-10859 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms				Material Handling And Spill Prevention		
Retention Ponds						
Ditches						

Comment: Partially plowed location with 8" of snow.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700405013	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5331036