

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2021

Submitted Date:

01/15/2021

Document Number:

688800849

FIELD INSPECTION FORM

 Loc ID 414270 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137
Findings:

- 18 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jordan, Reid		maralextechjr@gmail.com	
Fischer, Alex		alex.fischer@state.co.us	
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amo@maralexinc.com	All Inspections
,	970-563-4000	maralextech@gmail.com	All Inspections
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287557	WELL	PR	04/25/2007	GW	067-09255	GOSNEY 1-A	EI
294961	WELL	PR	08/22/2008	GW	067-09507	GOSNEY 4-A	EI
414273	WELL	PR	12/01/2010	GW	067-09798	GOSNEY 2-A	EI
463852	Domestic Tap	AC			-	Domestic Tap 14NWSW	EI

General Comment:

On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1A. For the most recent field inspection report of this facility, please refer to document #687904957.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Tank battery sign has previous operator's contact information posted.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>02/15/2021</u>
Type	WELLHEAD		
Comment:	Signs mounted to separator shacks. The location sign for the #2A does not have operator contact information posted.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>02/15/2021</u>
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels have previous operator's name and contact informaton posted.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: <u>02/15/2021</u>
Emergency Contact Number:			
Comment:	<input type="text" value="Previous operator's contact information posted on tank battery signage."/>		
Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Pump jacks, concrete foundations, and surrounding gravel are wet and stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>02/15/2021</u>
Produced Water	WELLHEAD	<= 1 bbl	
Comment:	The #4A and the #2A well heads and surrounding gravel are stained with white residue.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>02/15/2021</u>
In Containment: No			
Comment:	<input type="text"/>		
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing present.		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:	#1A well head.		

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Horizontal heated separator for the #1A does not appear to have a bird protector present.		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	02/15/2021
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic tap.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	#4A and #2A well heads.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Natural gas powered.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		37.193111,-107.582173
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-09798
067-06729
067-06570

AirsID

API Number	AirsID
------------	--------

067-09507

067-09255

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 287557 Type: WELL API Number: 067-09255 Status: PR Insp. Status: EI

Facility ID: 294961 Type: WELL API Number: 067-09507 Status: PR Insp. Status: EI

Facility ID: 414273 Type: WELL API Number: 067-09798 Status: PR Insp. Status: EI

Facility ID: 463852 Type: Domestic Tap API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on south load out line at tank battery.
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical containers.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1A. For the most recent field inspection report of this facility, please refer to document #687904957.</p> <p>During this inspection it appeared that the northernmost separator was missing a bird protector.</p> <p>The tank battery signs have the previous operator's contact information listed.</p> <p>The pump jacks and well heads for the #4A and #2A are stained and wet.</p>	hughesjo	01/15/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800850	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5331248