

GOLDEN EAGLE 21-07 API# 05-071-07680 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200807



PHOTO 1: THE BAR DITCH WAS RECONFIGURED TO ELIMINATE THE EROSION AND THE SOIL WAS COMPACTED WITH THE TIRE OF THE BACKHOE FOR STABILIZATION.

GOLDEN EAGLE 21-07 API# 05-071-07680 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200807



PHOTO 2: THE BAR DITCH WAS RECONFIGURED TO ELIMINATE THE EROSION AND THE SOIL WAS COMPACTED WITH THE TIRE OF THE BACKHOE FOR STABILIZATION.

GOLDEN EAGLE 21-07 API# 05-071-07680 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200807



PHOTO 3: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET

GOLDEN EAGLE 21-07 API# 05-071-07680 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200807



PHOTO 4: THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER RUN OFF WHICH IS DIRECTED TO THE CULVERT INLET ON THE MAIN ROAD.

GOLDEN EAGLE 21-07 API# 05-071-07680 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200807



PHOTO 5: THE EROSION ON THE ACCESS ROAD FILL SLOPE WAS BACK FILLED AND THE SOIL WAS COMPACTED.