

Inspection Photos

API: 099-06150

Operator: BERRY ENERGY INC

Inspection Date: 1/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing south toward the location. The access road continues thru the location. There are pipe risers that remain at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021

Inspection Photos



Photo 2. Pipe risers have not been removed at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021

Inspection Photos



Photo 4. Facing west toward the location. This area has not been reclaimed. Gravel remains and there are undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021

Inspection Photos



Photo 4. Facing southwest. The location has not re-established vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021

Inspection Photos



Photo 5. Facing north west at the northern side of the location. There is a pipe riser shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021

Inspection Photos



Photo 6. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06150 | Date: 1/12/2021