

Inspection Photos
Operator: Enduring
API: 067-08502
Date: 1/14/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is largely snow covered recovered, and revegetation is progressing with smooth brome.



Photo 3. View of the northern project area facing eastward.



Photo 4. View of the reference area comprised of irrigated grass field.