

Inspection Photos
Operator: Enduring
API: 067-07762
Date: 1/14/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is largely snow covered recovered, and revegetation is progressing with western wheatgrass, crested wheatgrass, smooth brome, and gambel oak.



Photo 3. View of Canada thistles within the southwestern project area. Approximately 75 individuals observed.



Photo 4. View of the reference area comprised of irrigated grass field.