

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/19/2021

Submitted Date:

01/19/2021

Document Number:

700702178

FIELD INSPECTION FORM
 Loc ID 335080 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282825	WELL	PR	05/19/2006	GW	045-11844	SPECIALTY 41C-28-692	PR
282826	WELL	PR	05/20/2006	GW	045-11843	SPECIALTY 31C-28-692	PR
282827	WELL	PR	05/18/2006	GW	045-11842	SPECIALTY 31A-28-692	PR
282828	WELL	PR	05/18/2006	GW	045-11841	SPECIALTY 41A-28-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 1/19/2021 at approximately 1130, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Specialty 41A, at Location # 335080 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Provide proof of tracking control BMP's
- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Two (2) Braden heads have telemetry for monitoring and Two (2) Braden heads have a port for manual gauge monitoring		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at gas meter run		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 6	
Comment:	All meters have been calibrated on location within the past year.	
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	OTHER	HEATED STEEL AST		,
Comment:	625 bbl tanks and Three (3) are NOT heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282825	Type:	WELL	API Number:	045-11844	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282826	Type:	WELL	API Number:	045-11843	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282827	Type:	WELL	API Number:	045-11842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282828	Type:	WELL	API Number:	045-11841	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: Tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Limited storm water inspection due to snow cover
 1. Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance
 2. No evidence of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 02/19/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702183	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5333317