

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2021

Submitted Date:

01/19/2021

Document Number:

700702179

**FIELD INSPECTION FORM**

Loc ID 335497 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294537	WELL	PR	08/14/2008	GW	045-15514	SPECIALTY 34B-21-692	PR
294538	WELL	PR	08/09/2008	GW	045-15513	SPECIALTY 44B-21-692	PR
294664	WELL	PR	08/15/2008	GW	045-15563	SPECIALTY 33B-21-692	PR
294665	WELL	PR	08/14/2008	GW	045-15564	SPECIALTY 33D-21-692	PR
294666	WELL	PR	08/12/2008	GW	045-15565	SPECIALTY 34D-21-692	PR
294667	WELL	PR	08/16/2008	GW	045-15566	SPECIALTY 43B-21-692	PR
294668	WELL	PR	08/09/2008	GW	045-15567	SPECIALTY 43D-21-692	PR
294669	WELL	PR	08/14/2008	GW	045-15568	SPECIALTY 44D-21-692	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 1/19/2021 at approximately 1230, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Specialty 34B, at Location # 335497 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Provide proof of tracking control BMP's
  - Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 8		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	294537	Type:	WELL	API Number:	045-15514	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294538	Type:	WELL	API Number:	045-15513	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294664	Type:	WELL	API Number:	045-15563	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294665	Type:	WELL	API Number:	045-15564	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294666	Type:	WELL	API Number:	045-15565	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294667	Type:	WELL	API Number:	045-15566	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294668	Type:	WELL	API Number:	045-15567	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	294669	Type:	WELL	API Number:	045-15568	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover  
 1. Location shows signs of lack of stabilization BMP's in some areas (rutting is present)  
 BMP's require maintenance  
 2. No evidence of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location  
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 02/19/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702184	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5333318">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5333318</a>