



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds unmanaged on location see pics		
Corrective Action:	Comply with weed management rules	Date:	01/29/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Red AG fencing		
Corrective Action:		Date:	

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Bird Protectors	# 1				
Ancillary equipment	# 1	automation			
Horizontal Heated Separator	# 1				
Bradenhead	# 1				
Plunger Lift	# 1				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,

Comment:		
Corrective Action:		
		Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 201012 Type: WELL API Number: 001-06415 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On 1/19/21 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Double USX ZM 17-11                      Company Name- P3                      API- 05-001-06415                      In Adams County Colorado.                      While there, I observed shut in well                      During this inspection the following possible compliance issues were observed:                      Weeds uncontrolled on location see pics                      Comply with weed management rules 1/29/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection weather conditions were sunny, windy, cold.                      This is a summary of inspection report.</p>	medinaj	01/19/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502152	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5333561">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5333561</a>