

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402576534

Date Received:
01/15/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
		vsantistevan@ogrisop.com
		efitzgerald@ogrisop.com
		rmack@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200807
Inspection Date: 11/10/2020 FIR Submit Date: 11/10/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308221

Location Name: GOLDEN EAGLE-633S67W Number: 21SWNE County: LAS ANIMAS
Qtrqtr: SWNE Sec: 21 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.160140 Longitude: -104.889480

FACILITY - API Number: 05-071-00 Facility ID: 264236

Facility Name: GOLDEN EAGLE Number: 21-07
Qtrqtr: SWNE Sec: 21 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.160140 Longitude: -104.889480

CORRECTIVE ACTIONS:

1 CA# 144302

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: _____

Response: CA COMPLETED Date of Completion: 01/08/2021

Operator Comment: THE BAR DITCH WAS RECONFIGURED TO ELIMINATE THE EROSION AND THE SOIL WAS COMPACTED WITH THE TIRE OF THE BACKHOE FOR STABILIZATION. THE SEDIMENT ACCUMULATION IN THE CULVERT INLET WAS REMOVED. THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER RUN

OFF FROM THE UPLAND WATERSHED. THE EROSION ON THE FILL SLOPE WAS BACK FILLED AND THE SOIL WAS COMPACTED.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Compacting soil for stabilization is not a long term stabilization method. Additional BMP's may be needed for stabilization.

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 1/15/2021 1:36:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402576534	FIR RESOLUTION SUBMITTED
402576537	PHOTO LOG

Total Attach: 2 Files