

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/20/2021

Submitted Date:

01/20/2021

Document Number:

700702188**FIELD INSPECTION FORM**Loc ID 335347 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259147	WELL	PR	09/01/2004	GW	045-07695	JACKSON 10-28	PR
259438	WELL	PR	09/01/2004	GW	045-07727	JACKSON 9-28	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 1/20/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Jackson 9-28, at Location # 335347 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

• Provide proof of tracking control BMP's

• Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	signage is located at tank battery		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 2			
Comment:	One (1) braden head is tied into sales			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	200 BBLs	STEEL AST		,	
Comment:	two (2) tanks ARE heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	Ignitor/Combustor	
------	-------------------	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 259147 Type: WELL API Number: 045-07695 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 259438 Type: WELL API Number: 045-07727 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Rip Rap						

Comment: Limited storm water inspection due to snow cover
 1. Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance.
 2. Provide proof of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 02/22/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702193	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334211