

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate, starting to fade and will need to be addressed in the near future		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	stained soil around WH		
Corrective Action:	comply with Rule 907.e	Date:	01/28/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 249081 Type: WELL API Number: 123-16883 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: braden head test is over 1 yr. and needs to be performed annually and well monitored monthly, submit bradenhead test information to COGCC engineering.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 1/14/2021 at approximately 1525 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Legg 14-22 at API #05-123-16883 in Weld County Colorado. While there, I observed a wellsite. PR at time of inspection. During this inspection the following possible compliance issues were observed: 907.e housekeeping: stained soil aroundWH, CA date 1-28-2021. See attached photos. Location: dry, Weather: clear, cold & windy. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	01/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402575652	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5330730
699303269	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5330729