



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Arrowhead 9

API: 05-103-05301

Inspection: 700405102



40.06872, -108.79408, 5372.1ft, 284°
01/21/2021 10:17:28 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well

Gas leak.

Arrowhead 9

API: 05-103-05301

Inspection: 700405102





40.06911, -108.7944, 5394.2ft, 5°
01/21/2021 10:10:34 AM



40.06912, -108.79439, 5395.1ft, 9°
01/21/2021 10:10:29 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank hatch

Gas leak.

Arrowhead 9

API: 05-103-05301

Inspection: 700405102



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Lower half of tank.

Arrowhead 9

API: 05-103-05301

Inspection: 700405102



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Tank.

Arrowhead 9

API: 05-103-05301

Inspection: 700405102