

# Final Reclamation Inspection

January 19, 2021

Operator: LILIS ENERGY INC - 10495

API: 05-039-06608

Inspection Document #: 697502465

Elbert County, CO

SWSE Section 10 T6S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**  
Department of Natural Resources


Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 1.** Google Earth aerial imagery taken 9/6/2013 during active operations.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 2.** Drone aerial imagery taken 1/19/2021 illustrates the location which has been fenced. The above red-circled area illustrates the approximate reclamation area still needing additional work, which is essentially the former production areas.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 3.** Close up photo taken from the southern location, facing South. Photo illustrates the lack of perennial vegetative growth. Annual, weedy growth has only established.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 4.** Photo taken from a portion of the access road, facing North. Photo illustrates the lack of perennial vegetative growth. Annual, weedy growth has only established.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 5.** Photo taken from a portion of the access road, facing South. See comments under Photo 4.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 6.** Close up photo taken from the northeastern location. Photo illustrates a List B Colorado noxious weed, Musk thistle.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 7.** Photo taken from the northwestern perimeter of location, facing East. Photo illustrates the silt fence is no longer in proper functioning condition.



**Photo 8.** Photo taken from the northwestern perimeter of location, facing South. See comments under Photo 6.

Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 9.** Reference photo taken east of the location, facing South.

