

**CAERUS PICEANCE LLC**  
**MF H17 696**  
**Location # 335825**



**CAERUS PICEANCE LLC**  
**MF H17 696**  
**Location # 335825**



**Perimeter ditch needs maintained.**

**CAERUS PICEANCE LLC**  
**MF H17 696**  
**Location # 335825**



**Storm water stalling at intersection of  
county road and access road.**

**CAERUS PICEANCE LLC**  
**MF H17 696**  
**Location # 335825**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present)**

**CAERUS PICEANCE LLC**  
**MF H17 696**  
**Location # 335825**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present)**

**CAERUS PICEANCE LLC**  
**MF H17 696**  
**Location # 335825**



**Drainage merging with road ditch is full of sediment.**