

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/19/2021

Submitted Date:

01/21/2021

Document Number:

696104223

**FIELD INSPECTION FORM**

Loc ID 305858 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**  
OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282976	WELL	SI	02/01/2019	OW	123-23589	PHINNEY 34-10	PA

**General Comment:**  
This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Plugging Operations / Cementing. Final plug.  
Battery: Inactive | Shut-down.  
Inactive Battery SE corner GPS coordinates: 40.497240, -104.528100

<b>Location</b>				
<b>Lease Road:</b>				
	Type Access			
	comment: Adequate			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type OTHER			
	Comment: Jobsite safety signage present.			
Corrective Action:				Date:
<b>Emergency Contact Number:</b>				
	Comment:	<input style="width: 100%;" type="text"/>		
	Corrective Action:	<input style="width: 100%;" type="text"/>		
				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
				corrective date
Type: Plunger Lift	# 0			
	Comment: Plugged & Abandoned   PA. Equipment removed.			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 282976 Type: WELL API Number: 123-23589 Status: SI Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Duco Cementers Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 2550'-1480'-778'-0' Cement Volume (sx): 580 sxs

Good Return During Job: YES Cement Type: Class "G-Neat" 15.8#

Comment: Workover Contractor: Ensign. Rig #318.  
 Cementing Contractor: Duco Cementers.

Reference:  
 Form 42 doc. #402576392. Notice of plugging start date: 01/18/2021. Approved.  
 Form 6 doc. #402561303. Notice of intent to Abandon date: 12/30/2020. Approved.

Final plug:  
 CREW TRAVEL TO LOC AND HELD SAFETY MEETING. CHECKED SIWP SICP 0PSI, SIBHP 0 PSI. RD WORK FLOOR AND TBG EQUIPMENT. ND BOP REMOVED WELLHEAD SURFACE CAP AND PACKING. PU 4 1/2 SUB AND UNLAND CASING. NU 8 5/8 SPOOL AND BOP. RU WORK FLOOR AND CASING EQUIPMENT BEGAN LAYING CASING DOWN TOTAL OF 59JTS OF 4 1/2 10.5# CASING ON FLOAT. RD CASING EQUIPMENT RU TBG EQUIPMENT BEGAN TITH WITH 40 STANDS FROM DERRIK PU 1 JT TOTAL OF 81 JTS IN HOLE @2550'. RU KELLY HOSE BROKE CIRCULATION AND CONDITIONED HOLE UNTIL CEMENTERS ARRIVED. MIRU DUCO CEMENT HELD SAFETY MEETING. SD PUMP ALLOWED WELL TO BALANCE OUT. RU DUCO PUMPED 5BBLS FRESH AHEAD BEGAN MIXING AND PUMPING 100 SXS (20.4bbls) OF 15.8ppg G NEAT CEMENT FROM 2550'-2300' DISPLACED TBG WITH 8.9BBLS FRESH MAINTAINED GOOD CIRCULATION THROUGHOUT PLUG. RD CEMENT LD 28JTS LEAVING 53JTS IN HOLE. RU CEMENTERS PUMPED 5BBLS FRESH AHEAD BEGAN MXING AND PUMPING 100 SXS(20.4bbls) OF 15.8# G NEAT CEMENT FROM 1680'-1480' DISPLACED TBG WITH 5.7BBLS FRESH MAINTAINED GOOD CIRCULTION THROUGHOUT PLUG. RD CEMENTERS LD 28 JTS LEAVING 25 JTS IN HOLE. RU CEMENTERS PUMPED 5BBLS FRESH AHEAD BROKE CIRCULATION BEGAN MIXING AND PUMPING 355 SXS (71bbls) OF 15.8ppg G NEAT CEMENT FROM 778'-SURFACE RETURNED 1BBL TO SURFACE MAINTANED GOOD CIRCULATION THROUGHOUT PLUG. RD CEMENTERS TIED IN TO CASING. LAYED DOWN REMAINING 25 JTS. WASHED UP WORK FLOOR AND TBG EQUIPMENT RIGGED IT DOWN. TOPED OFF WELL WITH 25 SXS (5BBLS) OF 15.8pppg G NEAT CEMENT, TIED IN CEMENTERS FOR WASH UP RDMO DUCO CEMENT. RD RIG PUMP AND TANKS CLEANED UP LOCATION. MOVE OUT.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 01/19/2021 at approximately 14:12 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: PHINNEY-66N64W /10SWSE                      Location ID: 305858                      Well Name: Phinney 34-10                      API: 05-123-23589                      Location County: Weld County, Colorado                      Weather: Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations / Cementing. Final plug.                      Battery: Inactive   Shut-down.                      Inactive Battery SE corner GPS coordinates: 40.497240, -104.528100</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/21/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104224	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335046">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335046</a>