

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2021

Submitted Date:

01/14/2021

Document Number:

688309446

FIELD INSPECTION FORM

 Loc ID 435195 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num:
Operator Information:
 OGCC Operator Number: 10706
 Name of Operator: D90 ENERGY LLC
 Address: 202 TRAVIS STREET #402
 City: HOUSTON State: TX Zip: 77002
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435194	WELL	TA	06/01/2020	OW	073-06563	JOHN CRAIG 2-2	SI

General Comment:

Reinspection, corrective action from inspection #688309446 was completed (Form 7s current through 10/1/2020)

Document #402492184 WARN -00 Letter IN PROCESS 9/17/2020 See inspection #688306549 about operator producing well to test well integrity. COGCC Engineer approved production test.

Document #402190896 Form 10 (CO)(CC) Type: Change of Operator IN PROCESS 3/25/2020

As Drilled Location: Footages Not Available Lat/Long: 39.212840 / -103.628100 Lat/Long Source: Field Measured. Survey and submit on Form 4 to COGCC database.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease signs at HWY 71 and access road		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	303-638-6096		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	steel panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas propane, AIRS Permit number posted at engine		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 435194 Type: WELL API Number: 073-06563 Status: TA Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: 10/1/2020 production/status reported to COGCC database.Corrective Action: See Warning Letter #402492184.Date: 12/31/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402575941	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5330992
688309508	D90 Energy John Craig 2-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5330976