

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2021

Submitted Date:

01/15/2021

Document Number:

688800849

FIELD INSPECTION FORM
 Loc ID 414270 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amo@maralexinc.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
,	970-563-4000	maralextech@gmail.com	All Inspections
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287557	WELL	PR	04/25/2007	GW	067-09255	GOSNEY 1-A	EI
294961	WELL	PR	08/22/2008	GW	067-09507	GOSNEY 4-A	EI
414273	WELL	PR	12/01/2010	GW	067-09798	GOSNEY 2-A	EI
463852	Domestic Tap	AC			-	Domestic Tap 14NWSW	EI

General Comment:

On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1A. For the most recent field inspection report of this facility, please refer to document #687904957.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Signs mounted to separator shacks. The location sign for the #2A does not have operator contact information posted.			
Corrective Action:	Install sign to comply with Rule 210.b.		Date:	02/15/2021
Type	BATTERY			
Comment:	Tank battery sign has previous operator's contact information posted.			
Corrective Action:	Install sign to comply with Rule 210.b.		Date:	02/15/2021
Type	TANK LABELS/PLACARDS			
Comment:	Tank labels have previous operator's name and contact informaton posted.			
Corrective Action:	Install sign to comply with Rule 210.d.		Date:	02/15/2021
Emergency Contact Number:				
Comment:	Previous operator's contact information posted on tank battery signage.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	The #4A and the #2A well heads and surrounding gravel are stained with white residue.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 02/15/2021
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Pump jacks, concrete foundations, and surrounding gravel are wet and stained.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 02/15/2021
In Containment: No				
Comment:				
<input checked="" type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Guard fencing present.			
Corrective Action:			Date:	
Equipment:				
Type: Horizontal Heated Separator	# 3			corrective date
Comment:				

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Horizontal heated separator for the #1A does not appear to have a bird protector present.		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	02/15/2021
Type: Plunger Lift	# 1		
Comment:	#1A well head.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic tap.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	#4A and #2A well heads.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Natural gas powered.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		37.193111,-107.582173
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-09798		
067-06729		
067-06570		

067-09507

067-09255

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>287557</u>	Type: <u>WELL</u>	API Number: <u>067-09255</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>294961</u>	Type: <u>WELL</u>	API Number: <u>067-09507</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>414273</u>	Type: <u>WELL</u>	API Number: <u>067-09798</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>463852</u>	Type: <u>Domestic Tap</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical containers.
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on south load out line at tank battery.

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1A. For the most recent field inspection report of this facility, please refer to document #687904957. During this inspection it appeared that the northernmost separator was missing a bird protector. The tank battery signs have the previous operator's contact information listed. The pump jacks and well heads for the #4A and #2A are stained and wet.	hughesjo	01/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402576370	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5331251
688800850	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5331248