

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2021

Submitted Date:

01/14/2021

Document Number:

696302858

FIELD INSPECTION FORM

Loc ID 432757 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432750	WELL	PR	11/12/2013	OW	123-37263	Pappenheim 6-62-23-0461BH	PR
432751	WELL	PR	12/11/2013	OW	123-37264	Pappenheim 6-62-23-0560BH	PR
432752	WELL	PR	11/12/2013	OW	123-37265	Pappenheim 6-62-23-0659CH	PR
432753	WELL	SI	04/01/2020	OW	123-37266	Pappenheim 6-62-23-0164BH	SI
432755	WELL	PR	10/30/2013	OW	123-37268	Pappenheim 6-62-23-0263BH	PR
432756	WELL	SI	06/01/2020	OW	123-37269	Pappenheim 6-62-23-0362BH	SI
433867	WELL	SI	09/01/2020	OW	123-37826	Pappenheim 6-62-23-0164CDH	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Pumping Units and North Separator, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	01/20/2021
Type	OTHER		
Comment:	Stained Soil at East VRU, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	01/29/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 3		corrective date
Comment:			
Corrective Action:		Date:	

Type: Gathering Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: VRT	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 7		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	500 BBLs	STEEL AST		40.479860,-104.292120
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type			
Comment:			
Corrective Action:			

Inspected Facilities				
Facility ID: 432750	Type: WELL	API Number: 123-37263	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 432751	Type: WELL	API Number: 123-37264	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 432752	Type: WELL	API Number: 123-37265	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 432753	Type: WELL	API Number: 123-37266	Status: SI	Insp. Status: SI
<u>Idle Well</u>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: SI				
Corrective Action:			Date:	
Facility ID: 432755	Type: WELL	API Number: 123-37268	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 432756	Type: WELL	API Number: 123-37269	Status: SI	Insp. Status: SI
<u>Idle Well</u>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: SI				
Corrective Action:			Date:	
Facility ID: 433867	Type: WELL	API Number: 123-37826	Status: SI	Insp. Status: SI
<u>Idle Well</u>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: SI				
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Stained Soil at East VRU, Unmarked Risers at North Separator/Heater Treater and West of Pumping Units	petrie	01/14/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402576027	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5331039
696302859	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5331024