



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 288978 Type: WELL API Number: 123-24722 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: At time of inspection flow line have been removed. Form 4 TA status is on file with the COGCC. No MIT on file. Noble Energy's Alternative Mechanical Integrity Assurance Program.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test:  Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure:  Fluid Type:   
End Surf Csg Pressure:

Comment: Submit reports.

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<u>Routine inspection.</u>	silverr	01/22/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693504240	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335470</a>