

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2021

Submitted Date:

01/22/2021

Document Number:

693200783**FIELD INSPECTION FORM**Loc ID 334940 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Caerus		COGCC.inspections@caerus oilandgas.com	All Piceance inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	Engineering Integrity Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267970	WELL	PR	06/01/2019	GW	045-09226	HMU 3-15A (I3)	EG
267974	WELL	PR	02/19/2004	GW	045-09229	HMU 3-16 (I3)	EG
267982	WELL	PR	02/19/2004	GW	045-09236	HMU 3-10 (I3)	EG
268005	WELL	PR	02/19/2004	GW	045-09238	HMU 3-15 (I3)	EG
268006	WELL	PR	02/19/2004	GW	045-09239	HMU 3-14A (3)	EI
478986	SPILL OR RELEASE	AC	01/11/2021		-	I3 Dumpline Release	EG

General Comment:[Engineering Integrity Inspection performed on January 22, 2021, in response to Supplemental form 19-release report Doc # 402568369](#)[For more information on release see form 19 document number 402568369 and inspection document](#)[See photo log](#)

Inspected Facilities

Facility ID: 267970 Type: WELL API Number: 045-09226 Status: PR Insp. Status: EG

Facility ID: 267974 Type: WELL API Number: 045-09229 Status: PR Insp. Status: EG

Flowline

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel
 Variance: No Age: 1-5 Yrs Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Wells were shut in at time of inspection

Flowline leak found on dump line

Provide Root Cause when information becomes available. Via FIRR and email to Western Integrity inspector

Corrective Action:

Date:

Facility ID: 267982 Type: WELL API Number: 045-09236 Status: PR Insp. Status: EG

Facility ID: 268005 Type: WELL API Number: 045-09238 Status: PR Insp. Status: EG

Facility ID: 268006 Type: WELL API Number: 045-09239 Status: PR Insp. Status: EI

Facility ID: 478986 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200785	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335548