

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2021

Submitted Date:

01/22/2021

Document Number:

701101078

FIELD INSPECTION FORMLoc ID 335814 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265355	WELL	PR	03/01/2019	GW	045-08989	CHEVRON 42-5D	PR
281978	WELL	PR	03/01/2019	GW	045-11607	CHEVRON 2F-4D	PR
281979	WELL	PR	03/01/2019	GW	045-11606	CHEVRON 12-4	PR

General Comment:**COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at CAERUS PICEANCE LLC, Chevron 42-5D, Location ID: 435733 in Garfield County, Colorado

Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

No evidence of tracking control BMP's.

N39.55098 W-108.12060 Sediment blockage in ditch.

N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet. Water not draining off road.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Main		
comment:	See storm water report.		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Bradenhead	# 3			
Comment:	Braden head accessible for monitoring.			
Corrective Action:				Date:
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 265355 Type: WELL API Number: 045-08989 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 281978 Type: WELL API Number: 045-11607 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 281979 Type: WELL API Number: 045-11606 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			N39.55348 W-108.11985 Sediment build up in culvert
				Vehicle Tracking	Fail	Location shows signs of lack of stabilization BMPs
Tracking Pad	Fail	Tracking Pad	Fail	Vehicle Tracking	Fail	No evidence of tracking control BMP's.
Gravel						
		Ditches	Fail			N39.55098 W-108.12060 Sediment blockage in ditch.
Berms	Pass					

Comment: Location shows signs of lack of stabilization BMP's in some areas (rutting is present).
 No evidence of tracking control BMP's.
 N39.55098 W-108.12060 Sediment blockage in ditch.
 N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet. Water not draining off road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
 Install, maintain or provide documentation of post construction management plan or BMP's.

Date: 02/06/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101079	Inspection 701101078 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335802