

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-------------------|-------|--|
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Panel x 2 | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-------------------------------|---------------|-------|-----------------|
| Type: Emission Control Device | # 2 | | corrective date |
| Comment: | Pilots are on | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |

| | | |
|---|-----|-------|
| Comment: Bradenhead valve is exposed at surface. | | Date: |
| Corrective Action: | | Date: |
| Type: Compressor | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 2 | |
| Comment: Automation array and ECD scrubber | | |
| Corrective Action: | | Date: |
| Type: Prime Mover | # 1 | |
| Comment: Natural gas engine on compressor | | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: Calibration card is current. | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 3 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Other | # 2 | |
| Comment: Wellhead and plunger lubricator leaks noted in prior inspection document #697002762 have been repaired. See attached photos. | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--------|-------|--|
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | , | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Paint | | | | | | | |
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |
| Berms | | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Venting: | | | | | | | |
| Yes/No | NO | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Flaring: | | | | | | | |
| Type | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Inspected Facilities

Facility ID: 299162 Type: WELL API Number: 123-29279 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697002917 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5336224 |