

Inspection Photos
Operator: Enduring
API: 067-08706
Date: 1/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Location largely snow covered. Taller perennial vegetation such as crested wheatgrass, western wheatgrass, and sand dropseed observable through the snow. Planted trees are largely dead.



Photo 3. View of the southern project area from the southeastern corner facing eastward.



Photo 4. View of dead tree within the project area, fencing and staking present and only dead wood remains.



Photo 5. View of the reference area comprised of sagebrush shrubland with scattered pinyon and juniper trees, mountain mahogany, James galleta, and purple threeawn.