

Inspection Photos
Operator: Enduring
API: 067-08652
Date: 1/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Location largely snow covered. Taller perennial vegetation such as blue grama, western wheatgrass, and sand dropseed observable through the snow.



Photo 3. View of the southern project area from the southeastern corner facing westward. Irrigation pipe from adjacent crop field is placed within the southern project area.



Photo 4. View of the reference area comprised of irrigated grass field (at right) and pinyon/juniper woodland with sagebrush understory (on the right).