



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                        | #   | Comment | Corrective Action | Date | corrective date |
|-----------------------------|-----|---------|-------------------|------|-----------------|
| Horizontal Heated Separator | # 1 |         |                   |      |                 |
|                             |     |         |                   |      |                 |
| Bradenhead                  | # 1 |         |                   |      |                 |
|                             |     |         |                   |      |                 |
| Bird Protectors             | # 1 |         |                   |      |                 |
|                             |     |         |                   |      |                 |
| Plunger Lift                | # 1 |         |                   |      |                 |
|                             |     |         |                   |      |                 |
| Vertical Separator          | # 1 |         |                   |      |                 |
|                             |     |         |                   |      |                 |

**Tanks and Berms:**

| Contents  | # | Capacity | Type      | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|--------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST |         |        |
|           |   |          |           |         |        |
|           |   |          |           |         |        |
|           |   |          |           |         |        |
|           |   |          |           |         |        |

Comment:

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                    |   |                     |                     |             |        |
|--------------------|---|---------------------|---------------------|-------------|--------|
| Earth              | Adequate  | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |   |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             | Date:  |
| Contents           | #   | Capacity            | Type                | Tank ID     | SE GPS |
| PRODUCED WATER     | 3   |                     |                     |             |        |
| Comment:           | 140 bbl open top, 80 BBL, 250 BBL. 80 BBL tank, and 250 BBL has different berm. Open top tank shares containment with oil tanks |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             | Date:  |
| <b>Paint</b>       |   |                     |                     |             |        |
| Condition          | Adequate  |                     |                     |             |        |
| Other (Content)    |   |                     |                     |             |        |
| Other (Capacity)   |   |                     |                     |             |        |
| Other (Type)       |   |                     |                     |             |        |
| <b>Berms</b>       |   |                     |                     |             |        |
| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |        |
| Earth              | Adequate  | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |   |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             | Date:  |
| <b>Venting:</b>    |   |                     |                     |             |        |
| Yes/No             | NO  |                     |                     |             |        |
| Comment:           |   |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             | Date:  |
| <b>Flaring:</b>    |   |                     |                     |             |        |
| Type               |   |                     |                     |             |        |
| Comment:           |   |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             | Date:  |

**Inspected Facilities**

Facility ID: 203224 Type: WELL API Number: 001-08733 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| This is an orphan well inspection.<br>Some weed growth around tanks, and wellhead.<br>MIT was failed in 2019.<br>At time of inspection weather condistions were windy, cold, overcast. | medinaj | 01/25/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 699502184    | pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5336574">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5336574</a> |