

Inspection Photos
Operator: Simcoe
API: 067-06067
Date: 1/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Location largely snow covered. Taller perennial vegetation such as smooth brome, western wheatgrass, and sand dropseed observable through the snow. Scattered musk thistles observed.



Photo 3. View of the western project area from the northwestern corner facing northward. Irrigation pipe from adjacent crop field is placed within the southern project area. Unmarked guyline anchors in the northwestern project area (see inset).



Photo 4. View of the reference area comprised of irrigated grass field, with smooth brome observed, although largely snow covered at this time.