

Inspection Photos  
Operator: Enduring  
API: 067-07644  
Date: 1/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass and sand dropseed observable through the snow.



Photo 3. View of the western project area from the northwestern corner facing southward.




Photo 4. View of Russian knapweeds within the project area. Approximately 500 individuals observed.





Photo 5. View of the reference area comprised of irrigated grass field, with smooth brome observed, although largely snow covered at this time. Location is also adjacent to a pinyon/juniper woodland with sagebrush understory. Reference area will be determined based on final land use.