

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2020

Submitted Date:

01/20/2021

Document Number:

697601169**FIELD INSPECTION FORM**Loc ID 318725 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Anadarko		COGCCinspections@Anadarko.com	
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412025	WELL	SI	06/01/2020	OW	123-30363	SALAZAR 25-20	EI
412027	WELL	PR	10/01/2019	OW	123-30364	SALAZAR 31-20	EI
416758	WELL	SI	06/01/2020	OW	123-31479	SALAZAR 22-20	EI
416759	WELL	PR	10/01/2019	GW	123-31480	SALAZAR 23-20	EI
479192	SPILL OR RELEASE	AC	01/12/2021		-	SPILL/RELEASE POINT	EI
479196	TANK BATTERY	AC	01/13/2021		-	Salazar Gas Unit 2 battery	EI

**General Comment:**

release of gas from flowline with fire ignited near emission control device

## Location

<b>Lease Road:</b>			
Type	Main		
comment:	adequate		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: on battery signs and wellhead signs

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
	Flow Line			
Comment:	initial form 19 reported as grade 1 gas leak			
Corrective Action:	supplemental spill report required within 10 days of spill discovery			Date: 01/21/2021

In Containment: No

Comment: spill/release reported and spill 479192 assigned as spill facility number in COGIS

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		

Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>412025</u>	Type: <u>WELL</u>	API Number: <u>123-30363</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>412027</u>	Type: <u>WELL</u>	API Number: <u>123-30364</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>416758</u>	Type: <u>WELL</u>	API Number: <u>123-31479</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>416759</u>	Type: <u>WELL</u>	API Number: <u>123-31480</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>479192</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>479196</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402579756	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334073</a>
697601170	emission control device near flowline release	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334055">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334055</a>
697601171	separators and emission control device	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334056">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334056</a>
697601172	produced water vessel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334057">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334057</a>
697601173	3 steel crude above ground storage tanks	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334058</a>
697601174	gas meter run (shed) & separators	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334059">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334059</a>
697601175	release at flowline from this well to battery during pressure test	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334060">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334060</a>