

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #2718 from entrance to location.



Photo #2719 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #2720 Stained soils located at wellhead.



Photo #2721 Ruts present on location due to lack of stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #2722 Ruts present on location due to lack of stabilization.