

Inspected Facilities

Facility ID: 261855 Type: WELL API Number: 123-20653 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 261856 Type: WELL API Number: 123-20652 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 699300912 & 699301182 in response to FIRR #402288362. Based on photos submitted be operator corrective actions have been completed. (photos attached to FIRR)	revasr	01/27/2021