

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2021

Submitted Date:

01/21/2021

Document Number:

701101069

**FIELD INSPECTION FORM**

Loc ID 335206	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258628	WELL	PR	09/01/2020	GW	045-07645	UNOCAL 24-16D	PR
258630	WELL	SI	09/01/2019	GW	045-07647	UNOCAL 14-16D	SI
258631	WELL	PR	09/01/2020	GW	045-07648	UNOCAL 13-16D	PR
288392	WELL	PR	09/01/2020	GW	045-13242	UNCOAL-ENCANA 14D-16D	PR
288393	WELL	PR	09/01/2020	GW	045-13241	UNOCAL-ENCANA 14B-16D	PR
288394	WELL	PR	09/01/2020	GW	045-13240	UNOCAL-ENCANA 14A-16D	PR
288401	WELL	PR	09/01/2020	GW	045-13233	UNCOAL-ENCANA 24B-16D	PR
288402	WELL	PR	09/01/2020	GW	045-13232	UNOCAL-ENCANA 24D-16D	PR

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at CAERUS PICEANCE LLC, UNOCAL-66S96W 16LOT 13, Location # 335206 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Location shows signs of lack of stabilization BMP's in some areas (rutting is present). Storm water stalling at intersection of county road and access road.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities				
Facility ID: 258628	Type: WELL	API Number: 045-07645	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 258630	Type: WELL	API Number: 045-07647	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment:				
Corrective Action:			Date:	
Facility ID: 258631	Type: WELL	API Number: 045-07648	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 288392	Type: WELL	API Number: 045-13242	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 288393	Type: WELL	API Number: 045-13241	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 288394	Type: WELL	API Number: 045-13240	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 288401	Type: WELL	API Number: 045-13233	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 288402	Type: WELL	API Number: 045-13232	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:			Date:	

<b>Producing Well</b>			
Comment:	Producing well		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Culverts	Pass			
Ditches	Pass					
		Gravel	Pass			
				Vehicle Tracking	Fail	
		Ditches	Pass			

Comment: Location shows signs of lack of stabilization BMP's in some areas (rutting is present). Storm water stalling at intersection of county road and access road.

Corrective Action: Install, maintain or provide documentation of post construction management plan or BMP's

Date: 02/05/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402580632	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334957">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334957</a>
701101070	Inspection 701101069 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334954">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334954</a>