

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2021

Submitted Date:

01/21/2021

Document Number:

701101071

**FIELD INSPECTION FORM**Loc ID 335653 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com |         |
| Kellerby, Shaun       |              | shaun.kellerby@state.co.us         |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 210805      | WELL | PR     | 08/10/1993  | GW         | 045-06563 | CHEVRON MV-25-17  | PR          |
| 289522      | WELL | PR     | 02/28/2007  | GW         | 045-13780 | CHEVRON GM 43-17  | PR          |
| 289523      | WELL | PR     | 02/28/2007  | GW         | 045-13779 | CHEVRON GM 343-17 | PR          |
| 289524      | WELL | PR     | 08/14/2007  | GW         | 045-13778 | CHEVRON GM 543-17 | PR          |

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W 17SWNE, Location # 335653 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Tank label is illegible.

Lumber debris at well head.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS  |       |            |
| Comment:           | Tank label is illegible   |       |            |
| Corrective Action: | "Comply with Rule 605.h.<br>(1).C. Tank capacity;<br>(2) Lettering on all new Tanks, and on any reapplied or modified labels, will be legible from a distance of 100 feet." | Date: | 04/22/2021 |
| Type               | WELLHEAD  |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | BATTERY   |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 |       |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |                             |       |            |
|--------------------|-----------------------------|-------|------------|
| Type               | DEBRIS                      |       |            |
| Comment:           | Lumber debris at well head. |       |            |
| Corrective Action: | Comply with Rule 606        | Date: | 02/05/2021 |

Overall Good: ☐**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                       |     |  |                 |
|-----------------------|-----|--|-----------------|
| Type: Bird Protectors | # 4 |  | corrective date |
|-----------------------|-----|--|-----------------|

|                                   |  |       |  |
|-----------------------------------|--|-------|--|
| Comment:                          |  |       |  |
| Corrective Action:                |  | Date: |  |
| Type: Bradenhead                  | # 4                                    |       |  |
| Comment:                          | Braden head accessible for monitoring. |       |  |
| Corrective Action:                |  | Date: |  |
| Type: Plunger Lift                | # 4                                    |       |  |
| Comment:                          |  |       |  |
| Corrective Action:                |  | Date: |  |
| Type: Horizontal Heated Separator | # 8                                    |       |  |
| Comment:                          |  |       |  |
| Corrective Action:                |  | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | 300 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|          |          |                     |                     |             |
|----------|----------|---------------------|---------------------|-------------|
| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal    | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment: |          |                     |                     |             |



**Inspected Facilities**Facility ID: 210805 Type: WELL API Number: 045-06563 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 289522 Type: WELL API Number: 045-13780 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 289523 Type: WELL API Number: 045-13779 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 289524 Type: WELL API Number: 045-13778 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 402580671    | INSPECTION SUBMITTED           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334991</a> |
| 701101073    | Inspection 701101071 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334989">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334989</a> |