

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2021

Submitted Date:

01/28/2021

Document Number:

690102272**FIELD INSPECTION FORM**Loc ID 335701 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		schuyler.hamilton@crestonepr.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
321	WELL	SI	12/01/2018	GW	014-20650	KATS 41-34	PA
322	WELL	SI	12/01/2018	GW	014-20651	KATS 42-34	PA
337	WELL	SI	12/01/2018	GW	014-20653	KATS 31-34	PA
338	WELL	SI	12/01/2018	GW	014-20654	KATS 6-4-34	PA
339	WELL	SI	12/01/2018	GW	014-20655	KATS 8-2-34	PA
250774	WELL	TA	11/01/2020	GW	014-18577	KATS 'B' UNIT 2	PA

General Comment:COGCC Engineering Integrity Inspection; Flowline Only
Photos uploaded.

Inspected Facilities

Facility ID: <u>321</u>	Type: <u>WELL</u>	API Number: <u>014-20650</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>322</u>	Type: <u>WELL</u>	API Number: <u>014-20651</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>337</u>	Type: <u>WELL</u>	API Number: <u>014-20653</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>338</u>	Type: <u>WELL</u>	API Number: <u>014-20654</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>339</u>	Type: <u>WELL</u>	API Number: <u>014-20655</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>250774</u>	Type: <u>WELL</u>	API Number: <u>014-18577</u>	Status: <u>TA</u>	Insp. Status: <u>PA</u>

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: COGCC Integrity Inspector on location on 1/27/2021; Inspector spoke with CPR contract personnel (NG) on site in the process of removing on location flowlines (dump flowlines/ process piping) associated with facility/ battery. (6) wells have been plugged and abandoned; wellhead flowlines (on location) are also scheduled to be removed. The facility has been decommissioned; all tanks and equipment removed. All flowlines on location scheduled for removal (COGCC forms submitted per 1100 series rules).

Note: Gas meter run and (3) associated gas gathering pipe risers are located on the east side of location. Communication with midstream operator (Anadarko) has been initiated in regard to the removal of this equipment.

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102273	Location signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339427
690102274	Excavation and flowlines removed; GMR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339428
690102275	PA well signs; excavations (view NE)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339429