

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2021

Submitted Date:

01/28/2021

Document Number:

699303364**FIELD INSPECTION FORM**Loc ID 331933 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268638	WELL	PR	09/01/2020	GW	123-21586	RODMAN BRUNZ 21-26	PR
433719	WELL	PR	07/08/2014	OW	123-37758	Rodman Bruntz 2D-26H	PR
433729	WELL	PR	07/10/2014	OW	123-37759	Rodman Bruntz 2E-26H C266	PR
433731	WELL	PR	07/08/2014	OW	123-37760	Rodman Bruntz 2C-26H	PR
438226	SPILL OR RELEASE	CL	06/26/2020		-	SPILL/RELEASE POINT	CL
450249	SPILL OR RELEASE	CL	07/16/2019		-	Rodman Bruntz 2E-26H 433729	CL

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate x 4		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	chainlink		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink x 2		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 7		

Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Separator	# 3		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	all appear to be plumbed to surface	Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	# 20		
Comment:	automation, electric panels and transformer	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card in meter house indicates current calibration	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	230 bbl

Other (Type)	
--------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	shares containment with condensate tanks		
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	800 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Wells Served By Facilities Above

API Number
123-38181
123-32182
123-32188
123-21586
123-32172
123-38186
123-37760
123-37759
123-19477
123-32168
123-32175
123-32197
123-37758

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 268638 Type: WELL API Number: 123-21586 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Corrective Action:

Date:

Facility ID: 433719 Type: WELL API Number: 123-37758 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Corrective Action:

Date:

Facility ID: 433729 Type: WELL API Number: 123-37759 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Corrective Action:

Date:

Facility ID: 433731 Type: WELL API Number: 123-37760 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438226 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

Facility ID: 450249 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

Producing Well

Comment: Form 19 Doc # 402430365 submitted on 6-26-2020.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 1/28/2021 at approximately 1115 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">Rodman Bruntz 26H-</p> <p>C66 at Location #331933 in Weld County Colorado.</p> <p>While there, I observed a multi well pad and tank battery. PR at the time of inspection.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location: snow covered, Weather: overcast/cloudy.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	01/28/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303365	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339579
699303366	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339580