

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate x 2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric panel and transformer have ag fence		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Ancillary equipment	# 3		
Comment:	automation, electric panels and transformer		
Corrective Action:		Date:	
Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 2		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	
Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 424428 Type: WELL API Number: 123-34027 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error
 Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 424431 Type: WELL API Number: 123-34029 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: TA form 21 Doc # 402458188 submitted on 8-4-2020.
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error
 Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____
 Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 1/28/2021 at approximately 1310 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Gobbler 1C-23HZ at Location #424427 in Weld County Colorado. While there, I observed a multi well pad. Gobbler 1N-23HZ PR at the time of inspection. Gobbler 1C-23HZ TA at time of inspection. During this inspection no compliance issues were observed: See attached photos. Location: snow covered, Weather: overcast/cloudy. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	01/28/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303372	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339583