

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2021

Submitted Date:

01/28/2021

Document Number:

699303379

FIELD INSPECTION FORM

Loc ID 419768 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298987	WELL	SI	06/01/2020	OW	123-29219	BADDING 40-26	SI
298988	WELL	SI	06/01/2020	OW	123-29220	BADDING 9-26	SI
298991	WELL	SI	06/01/2020	OW	123-29223	BADDING 20-26	SI
299175	WELL	SI	06/01/2020	OW	123-29281	BADDING 16-26	SI
419778	WELL	SI	06/01/2020	OW	123-32344	BADDING 15-26SX	SI
419782	WELL	SI	06/01/2020	OW	123-32347	BADDING 38-26	SI
419784	WELL	SI	06/01/2020	OW	123-32349	BADDING 10-26SX	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Ag panels		
Corrective Action:		Date:	

Equipment:

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Type: Bradenhead		# 7				
Comment:	all are exposed at surface					
Corrective Action:					Date:	
Type: Pump Jack		# 2				
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment		# 8				
Comment:	automation, electric panel and transformer					
Corrective Action:					Date:	
Type: Plunger Lift		# 4				
Comment:						
Corrective Action:					Date:	
Type: Prime Mover		# 2				
Comment:	electric motors					
Corrective Action:					Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 298987 Type: WELL API Number: 123-29219 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 298988 Type: WELL API Number: 123-29220 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 298991 Type: WELL API Number: 123-29223 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 299175 Type: WELL API Number: 123-29281 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment:

Corrective Action: Date: _____

Facility ID: 419778 Type: WELL API Number: 123-32344 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment:

Corrective Action: Date: _____

Facility ID: 419782 Type: WELL API Number: 123-32347 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment:

Corrective Action: Date: _____

Facility ID: 419784 Type: WELL API Number: 123-32349 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 1/28/2021 at approximately 1510 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location: Follow up inspection to Doc # 699302147. Badding 20-26SX at Location #419768 in Weld County Colorado. While there, I observed a multi well pad, SI at the time of inspection. During this inspection the following possible compliance issue has been addressed: 603.f housekeeping: trash (old fence posts/Ag fence) at PU bases has been removed. See attached photos 9 & 10. Location is snow covered, weather is cloudy. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	01/28/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303380	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339587